ROUTE/PROGRAM	Project ID Numbers	
ROOTE/TROOKAW	DB No.	TIP No.

206

### (40) Assiscunk Creek Bridge

94024

94024

#### LOCATION/DESCRIPTION

Bridge over Assiscunk Creek, proposed replacement

This project will provide for the proposed replacement of the existing structurally deficient bridge and associated roadway improvements.

SPONSOR: NJDOT
COUNTY: Burlington
MILEPOSTS: 29.54

STRUCTURE NO.: 0324162

MPO	Phase	Year	
DVRPC	FA	2002	
DVRPC	FSD	2003	

206

### (41) Crusers Brook Bridge

94060

94060

#### LOCATION/DESCRIPTION

Bridge over Crusers Brook, proposed replacement

This project will provide for the proposed replacement of the existing structure, which is in poor condition due to the condition of the superstructure and the inadequate deck geometry. Also, the structure is potentially scour critical, since the abutments are not founded on piles.

SPONSOR: NJDOT
COUNTY: Somerset
MILEPOSTS: 61.80

STRUCTURE NO.: 1810155

MPO	Phase	Year	
NJTPA	FSD	2002	

ROUTE/PROGRAM	Project ID Numbers	
ROOTE/T ROOM/IIV	DB No.	TIP No.

206 Arreton Road, Drainage

98423

4345

#### LOCATION/DESCRIPTION

Vicinity of Arreton Road, drainage improvements

It is proposed to replace the existing 36-inch culvert at Arreton Road with a 54-inch culvert as well as installing a Gabion lining to protect the eroded embankment on both sides of the roadway. A catch basin and connecting pipe to the existing culvert north c Arreton Road is proposed at the bottom of the driveway to reduce ponding on Route 206. South of Arreton Road, the embankment protection will be composed of Gabion Baskets and Reno Mattresses, to limit the extent of tree clearing needed. North of Arreton Road, the lining will be composed entirely of Gabion Baskets.

SPONSOR: NJDOT
COUNTY: Mercer
MILEPOSTS: 55.75 - 56.6
STRUCTURE NO.: N/A

МРО	Phase	Year
DVRPC	FSD	2002

206 Atsion Lake Dam

8906

8906

#### LOCATION/DESCRIPTION

This dam is classified as high hazard, Class 1 by NJDEP-DSS. This project will provide for proposed rehabilitation of the dam to address the following deficiencies: (1) timber gates and structural members of the spillway need to be replaced with concrete fixed crest spillway and (2) construct embankment protection measures or purchase the downstream properties to downgrade the hazard class to a 100-year storm.

SPONSOR: NJDOT
COUNTY: Burlington
MILEPOSTS: 7.20

STRUCTURE NO.: 0324150

MPO	Phase	Year
DVRPC	FA	2002
DVRPC	FSD	2003

ROUTE/PROGRAM	Project ID Numbers	
ROOTE/TROOK/IIV	DB No.	TIP No.

206 Burlington County, Route 30 to Route 68

9212

9212

#### LOCATION/DESCRIPTION

Route 30, Hammonton to Route 68, Mansfield, planning study

A planning study is ongoing for the development of a project for comprehensive corridor rehabilitation and operational improvements including, where appropriate, pavement rehabilitation, intersection improvements, drainage improvements, development of an access management plan, pedestrian improvements, signing and lighting improvements, and roadside rehabilitation.

SPONSOR: NJDOT

COUNTY: Burlington Atlantic

MILEPOSTS: 0 - 33.70 STRUCTURE NO.: N/A

МРО	Phase	Year	
DVRPC	FA	2002	
DVRPC	FSD	2003	

206 CSX Bridge Replacement

94059

94059

#### LOCATION/DESCRIPTION

This project will provide for the proposed replacement of the existing structure. The overall condition of the existing structure is listed as poor due to the severely disintegrated concrete, severe scaling and spalling of the substructure, and severe rusting and section loss of the superstructure components.

SPONSOR: NJDOT
COUNTY: Somerset
MILEPOSTS: 62.80

STRUCTURE NO.: 1810156

MPO	Phase	Year
NJTPA	FSD	2002

ROUTE/PROGRAM

Project ID Numbers
DB No. TIP No.

206 New Amwell Road

98506

98506

#### LOCATION/DESCRIPTION

New Amwell Road, identified safety problem

On the basis of statistical analysis, this location has been identified by the Safety Management System as having an apparent safety problem.

SPONSOR: NJDOT
COUNTY: Somerset
MILEPOSTS: 65.68
STRUCTURE NO.: N/A

МРО	Phase	Year
NJTPA	CD	2002
NJTPA	FA	2003

206

### **Princeton, Bicycle Improvements**

97027

#### LOCATION/DESCRIPTION

South of Stony Brook to Birch Avenue, proposed bicycle improvements

The proposed project may provide improvements to correct and/or eliminate existing gaps in primarily compatible segments of Route 206.

SPONSOR: NJDOT
COUNTY: Mercer
MILEPOSTS: 52.00 - 54.50
STRUCTURE NO.: N/A

МРО	Phase	Year
DVRPC	FA	2002

ROUTE/PROGRAM	Project ID Numbers	
ROOTE/TROOK/IIV	DB No.	TIP No.

#### 206 Route 30 to Route 68, Bicycle **Improvements**

97043

97043

#### LOCATION/DESCRIPTION

Route 30 to Route 68, proposed bicycle improvements

The proposed project may include intersection studies at Tabernacle Road and Pemberton Road on Route 206 to determine if elimination of the second lane is possible improve intersections with crosswalks, signage and pedestrian signals; widen shoulders at entrances and exits to traffic circle; and installation of "Share the Road" signs.

SPONSOR: NJDOT

COUNTY: **Burlington Atlantic** 

MILEPOSTS: 0 - 33.70 STRUCTURE NO.: N/A

МРО	Phase	Year
DVRPC	FA	2002
SJTPO	FA	2002
DVRPC	FSD	2003
SJTPO	FSD	2003

206 Southampton Twp., Drainage 96002

96002

#### LOCATION/DESCRIPTION

Vicinity of Jack's Run, proposed drainage improvements

An identified drainage problem results in periodic flooding. Conditions noted include the ditch behind Jamie's Auto Service has to be filled with water in order to build up enough force to flow downstream, causing water to back up in the culvert, flooding the road; the culvert under Route 206 is undersized.

SPONSOR: NJDOT COUNTY: Burlington MILEPOSTS: 18.40 STRUCTURE NO.:

MPO	Phase	Year
DVRPC	FA	2002
DVRPC	FSD	2003

ROUTE/PROGRAM	Project ID Numbers
KOOTE/T KOOKAM	DB No. TIP No.

206

### **Stony Brook Bridges**

326

#### LOCATION/DESCRIPTION

This project will provide for the proposed rehabilitation of the historic bridge (Route 20 over Stony Brook) and replacement of the adjacent structure (Route 206 over Flood Plain).

SPONSOR: NJDOT
COUNTY: Mercer
MILEPOSTS: 52.50

STRUCTURE NO.: 1129154 1129155

MPO	Phase	Year
DVRPC	FA	2002
DVRPC	FA	2003

206

## Sussex County, Bicycle Improvements

97038 970

97038

#### LOCATION/DESCRIPTION

Brighten Road to CR 517, Spring Street to CR 519, and Woodside Avenue to Winwood Avenue, proposed bicycle improvements

This proposed project may provide improvements to correct and/or eliminate existing gaps in a primarily bicycle compatible roadway section through rural town centers, possibly by providing a shared lane approximately 14-foot minimum. Gaps in existing sidewalks through town centers will also be corrected. Share the road signing would also be provided.

SPONSOR: NJDOT COUNTY: Sussex

MILEPOSTS: 103.30-103.50; 108.30-108.50; 109.18-109.25

STRUCTURE NO.: N/A

МРО	Phase	Year
NJTPA	CD	2002
NJTPA	FA	2003

ROUTE/PROGRAM	Project ID Numbers
KOOTE/T KOOKAM	DB No. TIP No.

206

### **Tuckerton Road, Drainage**

9375

9375

#### LOCATION/DESCRIPTION

Vicinity of Tuckerton Road, proposed drainage improvements

The proposed improvements include raising Route 206 as well as grading and repair of all existing ditches. The project will also include increasing the length and bottom widtl of the ditches abutting the highway and providing slopes to the outfall area. Existing drainage pipes will be replaced with larger pipes and additional outlets.

SPONSOR: NJDOT
COUNTY: Burlington
MILEPOSTS: 12.75
STRUCTURE NO.: N/A

МРО	Phase	Year
DVRPC	FSD	2002